

BSTHD1043 Radial Arm Saw Motor Starter is replaced by BSTHD1045


BSTHD1044 Dust Collector Motor Starter is replaced by BSTHD1046

BSTHD1045 and BSTHD 1046 are shipped as two components that will need to be assembled in order to be wired into the panel. Wiring and assembly shown below:

BSTHD1045

Radial Arm Saw Motor Starter

M1



BSTHD1046

Dust Collector Motor Starter

M2

